


COLOR CODE TIPS

PAPER CALIBRATION


1

Make sure bot is powered off, then place it in the black circle.




2

Press & hold bot's Power Button for 2-4 sec. until top light blinks white. Then, release Power Button.




3



Your bot blinks green when calibrated. If bot blinks red, start over from step 1. Evo also spins during calibration.

4



Press the Power Button to turn Bit back on. Evo powers on automatically after calibrating.

DRAWING LINES



Too Thin!




Too Thick!




Inconsistent!



Just Right



Too Close!



Just Right



Too Sharp!



Just Right



Just Right

DRAWING COLOR CODES



X
Codes on
colored lines



X
Different sizes




X
White spaces



X
Overlapping colors



X
Too dark



X
Single color squares
larger than 1/4"



✓
Single color squares
approx 1/4"
Codes on black lines

MARKERS


To draw any Color Code, you will need a combination of black, red, green and blue markers.




X
Dry Erase




X
Crayons



✓




X
Colored pencil




X
Highlighter

Ozobot Markers
Crayola Classic
Crayola Pastels
Sharpie Chisel Tips
(use light green and
light blue)


COLOR CODE PLACEMENT




X
Codes on corners



✓
Keep codes on straight lines
away from corners




X
Too close to
intersection



✓
Place codes away
from intersections



X
Codes too close



✓
Codes at least 1" apart



✓
Two-color codes need to
be at line end



✓
All other codes need black line
before and after

STICKERS




X
Codes on
colored lines




X
Codes on
corners



X
Not lined up



X
Too close



✓
Align with straight,
black lines
At least 1-inch from
corners, intersections,
and other codes

These calibration dots can be re-used for play on paper with Evo or Bit. **Cut along the dotted lines and fill circles in with black marker.**

Note: Do not laminate as your bot cannot properly calibrate on a laminated surface.



CALIBRATION DOT TEMPLATES

Evo | Bit

CALIBRATION DOT

How to Calibrate:

1. Make sure bot is powered off, then place it in the black circle.
2. Press & hold bot's Power Button for 2-4 sec. until top light blinks white. Then, release Power Button.
3. Your bot blinks green when calibrated. If bot blinks red, start over from step 1. Evo also spins during calibration.
4. Press the Power Button to turn Bit back on. Evo powers on automatically after calibrating.




ozobot

CALIBRATION DOT

How to Calibrate:

1. Make sure bot is powered off, then place it in the black circle.
2. Press & hold bot's Power Button for 2-4 sec. until top light blinks white. Then, release Power Button.
3. Your bot blinks green when calibrated. If bot blinks red, start over from step 1. Evo also spins during calibration.
4. Press the Power Button to turn Bit back on. Evo powers on automatically after calibrating.




ozobot

CALIBRATION DOT

How to Calibrate:

1. Make sure bot is powered off, then place it in the black circle.
2. Press & hold bot's Power Button for 2-4 sec. until top light blinks white. Then, release Power Button.
3. Your bot blinks green when calibrated. If bot blinks red, start over from step 1. Evo also spins during calibration.
4. Press the Power Button to turn Bit back on. Evo powers on automatically after calibrating.



ozobot

